

# T ECHNICAL INFORMATION

B6287


P 1/2

**Subject** ▶ Change of Cleaner plate assembly, Cleaner cover assembly, Air cleaner element November 2016  
Addition of M5x20 Hex socket head bolt  
Elimination of Indication label

**For Models** ▶ Makita: EM4350LH, EM4350LHG, EM4350UH, EM4350UHG, EM4351UH, EM4351UHG, EH043  
DOLMAR: MS-430.4 C, MS-430.4 U, MS-4300.4 U

**Country** ▶ All countries

**Description** ▶ Assembling way of Cleaner cover complete will be improved. Therefore, the relevant parts will be changed/ added. Indication label will be eliminated from Cleaner cover assembly.



## Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
221 (EH043: 116)	Cleaner plate assembly ----- 126117-2		1	No	Cleaner plate assembly ----- 123994-3		1	Interchangeable as a set
215 (EH043: 110)	Cleaner cover assembly ----- 126474-8		1	No	Cleaner cover assembly ----- 126523-1		1	
220 (EH043: 115)	Air cleaner element ----- 443173-0		1	No	Air cleaner element ----- 443196-8		1	
216 (EH043: 111)	Hex socket head bolt M5x20 ----- 266743-6		1	Yes	Hex socket head bolt M5x20 ----- 266743-6		2	
215 C10 (EH043: 110 C10)	Indication label ----- 801S44-5		1					Change of Air cleaner element from 443173-0 to 443196-8
—	Maintenance kit set ----- 196720-3		1	Yes	Maintenance kit set ----- 196720-3		1	
—	Maintenance kit set ----- 196721-1		1	Yes	Maintenance kit set ----- 196721-1		1	

## Implementation

From February 2017 production