



## **Cordless Fan**



# High-performance

330mm (13") Cordless Jobsite Fan













Charging time (3.0Ah)


1 to 2 batteries : 60minutes

DC18SF





Charging time (3.0Ah)



DC18SD

60minutes








	<u> </u>
attery capacity	5.0A
ontinuous use (minutes)	Hi: 100
	Mid: 160
	Lo: 340
imensions	315x480x
xWxH)	(12-3/8"x
et Weight*	4.7kg (10.
	4.5kg (9.8

( Idamon Abar								
	5.0Ah	4.0Ah	3.0Ah	2.0Ah	1.5Ah	1.3Ah		
:	100	75	55	40	30	25		
d:	160	125	90	65	50	40		
:	340	255	180	130	100	80		
5x480x600mm								
2-3/8"x18-7/8"x23-5/8")								
7ka (10 Albs) with RI 1830								





4.0Ah | 3.0Ah | 1.5Ah | 1.3Ah

Standard Equipment:

AC Adapter (Battery and Charger are sold separately.)

\*weight according to EPTA-Procedure 01/2003 Items of standard equipment and specifications may vary by country or area.

### Makita Corporation

3-11-8 Sumiyoshi-cho, Anjo, Aichi, 446-8502 Japan